EDUCATIONAL ASPIRATIONS FOR THE FUTURE

SCHOOL: STRACATHRO PRIMARY SCHOOL

AREA: Learning and Teaching Spaces (e.g. classrooms, areas of group work/private study,

internal and external P.E. / games areas)

actor:	Functionality	Rating
	To what extent do the facilities enhance/support:	
	learning, teaching and inclusion?	В
	flexible approaches to learning & teaching?	В
	effective use of resources?	В
	outdoor learning?	A
S	the development of creativity skills?	В
ace	the development of employability skills?	В
Sp	engagement and delivery of a full sports programme	D
ing	Accessibility	
act	How effective is Internal and external access to changing facilities?	D
Te	How accessible are facilities for community groups during and after the school day?	D
Learning & Teaching Spaces	Assess the availability of parking for the number of users.	С
Ë	Environmental Conditions	
eal	To what extent does the building make use of/support renewable energy?	D
_	Safety & Security	
	How confident are we that all users are safe and secure?	В
	Fixed Furniture and Fittings	В
		I 6
	To what extent does the infrastructure support digital learning?	D
	Assess the suitability of storage to meet the needs of all users.	В
	OVERALL RATING	C
	Comments	
-	Functionality	
	Classroom are adequate in size but would benefit from additional furniture such as room dividers et	e This
	would help to create activity areas within the classrooms and provide pupils with the facilities that w	
	encourage creative learning and teaching.	voulu
	encourage creative rearring and teaching.	
	The location of the nursery and the P4-7 is not ideal as the only route of access to these areas is three	nugh a
	classroom. This can be disruptive towards pupils and teachers within these areas.	Jugira
	classicom. This can be distuptive towards pupils and teachers within these areas.	
	The school benefits from excellent outdoor learning facilities with a mixture of grassed and tarmack	ed surfar
	as well as an abundance covered areas that support group and individual activities.	CO 30110
	as well as all abundance covered areas that support group and individual activities.	
		orting
	Stracathro Primany School has no indoor sports facilities and has an unsuitable outdoor space for sp	UIGHE
	Stracathro Primary School has no indoor sports facilities and has an unsuitable outdoor space for sp	-
	activities due to the placement of trees and rabbit holes. This is detrimental to the schools ability to	-
	The state of the s	-
	activities due to the placement of trees and rabbit holes. This is detrimental to the schools ability to full sports programme. Pupils use the facilities at Edzell Primary School for P.E.	-
	activities due to the placement of trees and rabbit holes. This is detrimental to the schools ability to full sports programme. Pupils use the facilities at Edzell Primary School for P.E. Accessibility	-
	activities due to the placement of trees and rabbit holes. This is detrimental to the schools ability to full sports programme. Pupils use the facilities at Edzell Primary School for P.E.	-
	activities due to the placement of trees and rabbit holes. This is detrimental to the schools ability to full sports programme. Pupils use the facilities at Edzell Primary School for P.E. Accessibility There are no changing facilities within the school building or the grounds.	deliver
	activities due to the placement of trees and rabbit holes. This is detrimental to the schools ability to full sports programme. Pupils use the facilities at Edzell Primary School for P.E. Accessibility There are no changing facilities within the school building or the grounds. There is no suitable space within the school that can be used for community use other than the dini	deliver
	activities due to the placement of trees and rabbit holes. This is detrimental to the schools ability to full sports programme. Pupils use the facilities at Edzell Primary School for P.E. Accessibility There are no changing facilities within the school building or the grounds.	deliver a
	activities due to the placement of trees and rabbit holes. This is detrimental to the schools ability to full sports programme. Pupils use the facilities at Edzell Primary School for P.E. Accessibility There are no changing facilities within the school building or the grounds. There is no suitable space within the school that can be used for community use other than the dini	ng hall,

available parking on the road, this is far from ideal due to this being a rural road.

Environmental Conditions

The school supports no form of renewable energy.

Safety and Security

Although these areas are reasonably risk free, the classrooms act as access routes into other areas.

The nursery area is divided into to separate spaces. This makes observation within the nursery difficult and has resulted in an extra staff member being employed. Consideration should be given to to prospect of the wall dividing these two areas being knocked through, creating one spacious area that can be easily observed.

Fixed Furniture and Fittings

The schools infrastructure is inadequate and does not support digital learning. The schools geographical location means there is no access to Wi-Fi, thus inhibiting pupils in terms of being able to access information via tablets etc.

The school has sufficient storage but would welcome more.

EDUCATIONAL ASPIRATIONS FOR THE FUTURE

SCHOOL: STRACATHRO PRIMARY SCHOOL

AREA: Internal Social Spaces (e.g. pupil social areas, dining, common rooms, staffrooms)

actor:	Functionality	Rating
Internal Social	How far can the facilities support multiple users during and after the school day?	C
	Accessibility	p-book common
	How accessible are facilities for community groups during and after the school day?	C
	Safety & Security	232
	How confident can we be that all users are safe and secure?	В
	Fixed Furniture and Fittings	
	Assess the suitability of furniture & fittings for community use	C
	To what extent is there sufficient storage to meet the needs of multiple users?	В
	OVERALL RATING	С
	Comments Functionality	
	P1-3 classroom and the library. This means the staffroom largely goes unused. The dining hall is insu size and is only accessible via the P4-7 classroom.	
	size and is only accessible via the P4-7 classibolit.	
	Accessibility	
	The school is not open to community groups during school hours. Although the dining can potentiall	-
	by the community, this area is small and has no direct external access. This means community group	
	access this area by entering the building at the reception and walking through the P4-7 classroom, p	otentiall
	coming into contact with sensitive or confidential information.	
	Safety and Security All appropriate measures have been taken to ensure the building is safe and secure.	
	Safety and Security	
	Safety and Security All appropriate measures have been taken to ensure the building is safe and secure.	
	Safety and Security All appropriate measures have been taken to ensure the building is safe and secure. Fixed Furniture and Fittings	
	Safety and Security All appropriate measures have been taken to ensure the building is safe and secure. Fixed Furniture and Fittings Although the dining hall has the potential to be used by community groups, there is no suitable s	seat

EDUCATIONAL ASPIRATIONS FOR THE FUTURE

SCHOOL: STRACATHRO PRIMARY SCHOOL

AREA: Internal Facilities (e.g. reception/administration/office/ meeting/ circulation space, resource/ staff bases,

library, toilets)

actor:	Functionality	Rating
	How far can the facilities support multiple users during and after the school day?	C
Internal Facilities	Accessibility	
	How accessible are facilities for community groups during and after the school day?	С
	Environmental Conditions	A TOTAL
	To what extent is 'noise' an issue?	A
	Safety & Security	31000
	How confident can we be that all users are safe and secure?	В
	To what extent does the environment have an impact on issues of confidentiality?	С
_	Fixed Furniture and Fittings	
	Assess the suitability of furniture & fittings for community use	С
	To what extent is there sufficient storage to meet the need of multiple users?	В
	OVERALL RATING	В
	Comments Functionality	
	Although there is a secure entry system, there is no reception desk or holding area with a reception l	aateb
	Action Bit there is a secure entry system, there is no reception desk of holding area with a reception i	ioteit.
	passed its life expectancy and should be replaced with a more suitable extension with level access. The head teachers office is located on the first floor and is only accessible by walking through the P1 classroom and the library. This means it largely goes unused and is currently being used as a storage	
	resources. The head teachers office should located near the reception and should be easily accessible	
	resources. The head teachers office should located near the reception and should be easily accessibl visitors/parents. The head teacher refuses to take visitors/parents into this area due to the implications in terms of his	e for any
	resources. The head teachers office should located near the reception and should be easily accessibl visitors/parents.	e for any
	resources. The head teachers office should located near the reception and should be easily accessibl visitors/parents. The head teacher refuses to take visitors/parents into this area due to the implications in terms of his walk through classrooms. This means the school office is currently used by the secretary and the head	e for an
	resources. The head teachers office should located near the reception and should be easily accessibl visitors/parents. The head teacher refuses to take visitors/parents into this area due to the implications in terms of his walk through classrooms. This means the school office is currently used by the secretary and the heat teaching. This makes dealing with confidential matters difficult.	e for any
	resources. The head teachers office should located near the reception and should be easily accessible visitors/parents. The head teacher refuses to take visitors/parents into this area due to the implications in terms of his walk through classrooms. This means the school office is currently used by the secretary and the heat teaching. This makes dealing with confidential matters difficult. Accessibility The spaces are not suitable for the use of community groups. Environmental Conditions	e for any
	resources. The head teachers office should located near the reception and should be easily accessible visitors/parents. The head teacher refuses to take visitors/parents into this area due to the implications in terms of he walk through classrooms. This means the school office is currently used by the secretary and the heat teaching. This makes dealing with confidential matters difficult. Accessibility The spaces are not suitable for the use of community groups.	e for any
	resources. The head teachers office should located near the reception and should be easily accessible visitors/parents. The head teacher refuses to take visitors/parents into this area due to the implications in terms of his walk through classrooms. This means the school office is currently used by the secretary and the heat teaching. This makes dealing with confidential matters difficult. Accessibility The spaces are not suitable for the use of community groups. Environmental Conditions	e for any
	resources. The head teachers office should located near the reception and should be easily accessible visitors/parents. The head teacher refuses to take visitors/parents into this area due to the implications in terms of his walk through classrooms. This means the school office is currently used by the secretary and the heat teaching. This makes dealing with confidential matters difficult. Accessibility The spaces are not suitable for the use of community groups. Environmental Conditions There are no issues with noise.	e for any aving to id
	resources. The head teachers office should located near the reception and should be easily accessible visitors/parents. The head teacher refuses to take visitors/parents into this area due to the implications in terms of his walk through classrooms. This means the school office is currently used by the secretary and the heat teaching. This makes dealing with confidential matters difficult. Accessibility The spaces are not suitable for the use of community groups. Environmental Conditions There are no issues with noise. Safety and Security	e for any aving to d
	resources. The head teachers office should located near the reception and should be easily accessible visitors/parents. The head teacher refuses to take visitors/parents into this area due to the implications in terms of his walk through classrooms. This means the school office is currently used by the secretary and the heat teaching. This makes dealing with confidential matters difficult. Accessibility The spaces are not suitable for the use of community groups. Environmental Conditions There are no issues with noise. Safety and Security Although the school has a secure entry system, there is no holding area with a reception hatch. This	e for any aving to ad
	resources. The head teachers office should located near the reception and should be easily accessible visitors/parents. The head teacher refuses to take visitors/parents into this area due to the implications in terms of his walk through classrooms. This means the school office is currently used by the secretary and the heat teaching. This makes dealing with confidential matters difficult. Accessibility The spaces are not suitable for the use of community groups. Environmental Conditions There are no issues with noise. Safety and Security Although the school has a secure entry system, there is no holding area with a reception hatch. This once a visitor/parent has been granted entry into the building, they have the potential to access every significant in the security into the building, they have the potential to access every significant into the security into the building, they have the potential to access every significant into the security into the building, they have the potential to access every significant into the security into the building, they have the potential to access every significant into the security into the building into the security into the building into the potential to access every significant into the security into the building into the security into the building into the security into the building into the potential to access every significant into the security into the building into the security into the security into the building into the security into the building into the security into	e for an
	resources. The head teachers office should located near the reception and should be easily accessible visitors/parents. The head teacher refuses to take visitors/parents into this area due to the implications in terms of his walk through classrooms. This means the school office is currently used by the secretary and the heat teaching. This makes dealing with confidential matters difficult. Accessibility The spaces are not suitable for the use of community groups. Environmental Conditions There are no issues with noise. Safety and Security Although the school has a secure entry system, there is no holding area with a reception hatch. This once a visitor/parent has been granted entry into the building, they have the potential to access ever the school. Consideration should be given to providing the school with a holding area. There are no meeting rooms or easily accessible spaces that can be used do deal with confidential means the school with a holding area.	e for and aving to id means t ry area
	resources. The head teachers office should located near the reception and should be easily accessible visitors/parents. The head teacher refuses to take visitors/parents into this area due to the implications in terms of his walk through classrooms. This means the school office is currently used by the secretary and the heat teaching. This makes dealing with confidential matters difficult. Accessibility The spaces are not suitable for the use of community groups. Environmental Conditions There are no issues with noise. Safety and Security Although the school has a secure entry system, there is no holding area with a reception hatch. This once a visitor/parent has been granted entry into the building, they have the potential to access eve the school. Consideration should be given to providing the school with a holding area.	e for an aving to d

These areas currently have sufficient storage but the school would welcome more.

EDUCATIONAL ASPIRATIONS FOR THE FUTURE

SCHOOL: STRACATHRO PRIMARY SCHOOL

AREA: External Social Spaces (e.g. play, covered, seated areas)

Factor:	Functionality	Rating
External Social	How far can the facilities support multiple users during and after the school day?	A
	To what extent do the facilities support outdoor learning?	A
	Accessibility	
	How accessible are facilities for community groups during and after the school day?	В
	Safety & Security	
Exte	How confident are we that all users are safe and secure?	C
	Fixed Furniture and Fittings	
	How far do the facilities support engagement in and delivery of a full sport programme?	D
	OVERALL RATING	В
	The school benefits from excellent outdoor learning facilities that challenge and stimulate pupils. The	
	facilities consist of various covered areas, seated areas and an outdoor classroom. This space also propuls and teachers with visually stimulating agricultural views. Accessibility The school grounds are not accessible for community groups during school hours but could potential	lly be use
	pupils and teachers with visually stimulating agricultural views. Accessibility	lly be use
	pupils and teachers with visually stimulating agricultural views. Accessibility The school grounds are not accessible for community groups during school hours but could potential outwith school hours. The grounds are very limited in terms of providing a suitable space for sporting	lly be use g activitie

EDUCATIONAL ASPIRATIONS FOR THE FUTURE

SCHOOL: STRACATHRO PRIMARY SCHOOL

AREA: External Facilities (e.g. car parks, bike sheds, drop-off areas, storage facilities)

actor:	Functionality	Rating	
External Facilities	How far can the facilities support multiple users during and after the school day?	C	
	Accessibility		
	How effective is external access to changing facilities?	D	
	Assess the availability of parking for the number of users.	C	
	Environmental Conditions		
	Reference to any external factors affecting the area e.g. light/noise pollution.	A	
	Also, does use outside of the school day affect neighbours?	A	
xte	Safety & Security	100	
	How confident are we that all users are safe and secure?	С	
	Fixed Furniture and Fittings		
	Assess the suitability of storage to meet the needs of all users	В	
	OVERALL RATING	В	
e w	Comments		
	Functionality/Accessibility		
	means parking is not even adequate for everyday staff. Although staff can park on the rural road, the from ideal. There is also no drop off area and no turning circle to ease congestion at the start/end of school day.		
	from ideal. There is also no drop off area and no turning circle to ease congestion at the start/end of		
	from ideal. There is also no drop off area and no turning circle to ease congestion at the start/end o school day.		
	from ideal. There is also no drop off area and no turning circle to ease congestion at the start/end of school day. The car park would not provide a sufficient amount of spaces for community use either.		
	from ideal. There is also no drop off area and no turning circle to ease congestion at the start/end of school day. The car park would not provide a sufficient amount of spaces for community use either. Bike shed facilities are adequate. There are no changing facilities within the school or the school grounds. Environmental Conditions	of the	
	from ideal. There is also no drop off area and no turning circle to ease congestion at the start/end of school day. The car park would not provide a sufficient amount of spaces for community use either. Bike shed facilities are adequate. There are no changing facilities within the school or the school grounds.	of the	
	from ideal. There is also no drop off area and no turning circle to ease congestion at the start/end of school day. The car park would not provide a sufficient amount of spaces for community use either. Bike shed facilities are adequate. There are no changing facilities within the school or the school grounds. Environmental Conditions There have been no issues with light/noise pollution nor has there been any complaints received by	of the	
	from ideal. There is also no drop off area and no turning circle to ease congestion at the start/end of school day. The car park would not provide a sufficient amount of spaces for community use either. Bike shed facilities are adequate. There are no changing facilities within the school or the school grounds. Environmental Conditions There have been no issues with light/noise pollution nor has there been any complaints received by neighbours.	of the borderin	
	from ideal. There is also no drop off area and no turning circle to ease congestion at the start/end of school day. The car park would not provide a sufficient amount of spaces for community use either. Bike shed facilities are adequate. There are no changing facilities within the school or the school grounds. Environmental Conditions There have been no issues with light/noise pollution nor has there been any complaints received by neighbours. Safety and Security The perimeter boundary wall is too low and is adjacent to a rural road. Suitable perimeter fencing we gates is essential in ensuring the safety of all pupils and staff. There is not CCTV system and no perimeter.	of the borderin	